



ACCO Brands
Four Corporate Drive
Lake Zurich, IL 60047-8997
Tel 800.790.7787

GBC SERVICE TECHNICAL BULLETIN

The firmware for the Punch G2 has been updated for compatibility with Wire Binder G1. It is only necessary to update the Punch G2 firmware if the configuration will also include a Wire Binder G1. However, the firmware versions listed below can also be used when only a Punch G2 is to be installed.

Firmware Versions as of 2/21/2019:

Punch G2

Main: 02.00

Comms: 02.01

Wire Binder G1

Processor A: 01.02

Processor B: 01.01

Processor C: 01.01